

Site CBSS11C: Cobequid Trail

Date Assessed: 07/02/02

GPS Coordinates: N 45° 21' 6.2''
W 63° 24' 23.8''

Crossing Status: Partial Restriction.

Road Crossing: Culvert, corrugated steel,
~1.35m wide

Crossing Condition: Structure is intact.

Restriction Indicators:

Difference in water level
Bank slumping
Scour pools
Divergent channel
Slack water

Downstream of Crossing

Creek: ~1m wide with smooth, straight flow.

Land: Marshland.

Upstream of Crossing

Creek: ~1m wide with angular/smooth, straight flow.

Land: Active agricultural land use.

Comments: Replace with larger opening




Figure 1.




Figure 2:
Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 94001-70