

Site CBSS13C: Beaver Brook (Old Barns)

Date Assessed: 07/02/02

GPS Coordinates: N 45° 20' 44.2''
W 63° 23' 27.1''

Crossing Status: No restriction.

Road Crossing: Culvert, wooden, open bottom, 4m wide

Crossing Condition: Structure is intact but showing wear

Restriction Indicators: None

Downstream of Crossing

Creek: 5.6m wide with smooth, straight flow.

Land: Active agricultural land.

Upstream of Crossing

Creek: 4m wide with smooth, straight flow.

Land: Active agricultural land.

Comments: Assessment of downstream restrictions is needed. This site is located in an agricultural dykeland.




Figure 1.



Figure 2.



Figure 3.




Figure 4:
Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 94001-71