

Site CBSS14C: Black Rock**Date Assessed:** 07/02/02

GPS Coordinates: N 45° 19' 13.2''
W 63° 28' 37.8''

Crossing Status: Complete restriction.

Road Crossing: Partial wooden Aboiteau. Old type of aboiteau (i.e. No tide gates, just blockage). Has partial blocking on downstream side restricting saltwater flow to upstream side.

Crossing Condition: Structure is in poor condition.

Restriction Indicators:
Difference in stream width
Slack water

Downstream of Crossing

Creek: 2.8m wide with smooth, straight flow.

Land: Active and abandoned agricultural land use.

Upstream of Crossing

Creek: ~1.8m wide with smooth, straight flow.

Land: Active and abandoned agricultural land use.

Comments: Aboiteau should be replaced with a culvert to allow tidal flow.





Figure 1.



Figure 2.



Figure 3.



Figure 4.



Figure 5.




Figure 6:
Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 94002-2