

**Site CBSS2A:** McLure Brook (Cobequid Trail)

**Date Assessed:** 06/27/02

**GPS Coordinates:** N 45° 22' 5.4''  
W 63° 19' 28.1''

**Crossing Status:** Complete Restriction.

**Road Crossing:** Aboiteau, cement, 3 tide gates, 1.6m each

**Crossing Condition:** Structure is intact.

**Restriction Indicators:**

Difference in stream width  
Difference in water level  
Bank slumping  
Scour pool  
Slack water  
Tide gate/aboteau

**Downstream of Crossing**

**Creek:** 12.9m wide with smooth, straight flow.


**Land:** Directly flows into the Bay

**Upstream of Crossing**

**Creek:** 9m wide with smooth, straight flow.

**Land:** Inactive agricultural land

**Comments:** This aboteau is located along side site CBSS3A and should be considered together with site CBSS1C located just upstream. Assessment of land use should be made at this site to determine if tide gates can be opened and to what degree would flooding occur. If it is not possible to open the tide gates, fish passages should still be addressed.





**Figure 1.**



**Figure 2.**



**Figure 3.**



Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04312-23