

Site CBSS8C: McNutt Brook (Cobequid Trail)

Date Assessed: 07/17/02

GPS Coordinates: N 45° 21' 38.9''
W 63° 22' 10.5''

Crossing Status: Partial restriction.

Road Crossing: Culvert, corrugated, ~2m wide

Crossing Condition: Structure is intact. Rock banking around culvert to prevent erosion.

Restriction Indicators:
Difference in water level
Difference in stream width
Bank slumping

Downstream of Crossing

Creek: Opens into Bay

Land: Mudflats

Upstream of Crossing

Creek: ~3.5m with smooth, straight flow.

Land: Unused agricultural land, wooded area.

Comments: Culvert is rusting out needs to be replaced




Figure 1.



Figure 2.




Figure 3: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 94001-20