

Site CBSS9C: McNutt Brook

Date Assessed: 06/28/02

GPS Coordinates: N 45° 21' 36.5''
W 63° 22' 7.8''

Crossing Status: Partial Restriction.

Road Crossing: Culvert, corrugated steel

Crossing Condition: Structure is intact.

Restriction Indicators:

Difference in stream width

Difference in water level

Bank slumping

Scour pool

Downstream of Crossing

Creek: 4.9m wide with smooth, straight flow.

Land: Residential, unused agricultural land with marsh vegetation evident.

Upstream of Crossing

Creek: ~1.2m wide with smooth, straight flow.

Land: Marshland and wooded area.

Comments: Replace culvert with a larger opening.






Figure 1.



Figure 2.



Figure 3.




Figure 4: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 94001-20