

Site SH1C: Princeport

Date Assessed: 10/07/02

GPS Coordinates: N 45° 16' 35.6''
W 63° 27' 35.3''

Crossing Status: Partial Restriction

Road Crossing: Culvert, wooden box,
1.8m

Crossing Condition: Intact

Restriction Indicators:
Difference in water level
Difference in vegetation
Bank slumping

Downstream of Crossing

Creek: 3.6m wide, smooth straight flow,
some bank slumping.

Land: Wooded area, some marsh
vegetation

Upstream of Crossing

Creek: 4.3m wide, smooth straight flow

Land: Wooded area

Comments: Consideration should be made to enlarging culvert opening.




Figure 1



Figure 2



Figure 3




Figure 4: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 94011-3