

**Site SH8B:** Shubenacadie River (Route 2)

**Date Assessed:** 21/06/02

**GPS Coordinates:** N 45° 5' 25.5''  
W 63° 24' 6.1''

**Crossing Status:** No Restriction

**Road Crossing:** Bridge, 82m opening.  
There is also a railway bridge further downstream that does not appear to be causing a restriction.

**Crossing Condition:** Intact

**Restriction Indicators:** None

### Downstream of Crossing

**Creek:** 88m wide, smooth, straight flow

**Land:** Residential, active farmland, railway crossing

### Upstream of Crossing

**Creek:** 88m wide, smooth, straight flow

**Land:** Residential, active farmland, dyke running along side of the river

**Comments:** Maintain size of opening



Figure 1




Figure 2



Figure 3



Figure 4\



**Figure 5: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)**

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 94017-60