

**Site ST4B:** Big Meadow Brook

**Date Assessed:** 21/06/02

**GPS Coordinates:** N 45° 9' 30.5''  
W 63° 20' 12.3''

**Crossing Status:** No Restriction

**Road Crossing:** Bridge, wooden, 8m opening

**Crossing Condition:** Intact

**Restriction Indicators:** None

**Downstream of Crossing**

**Creek:** 5.8m wide, smooth, straight flow

**Land:** Marshland, active farmland along one side of creek

**Upstream of Crossing**

**Creek:** 13.4m wide, smooth, straight flow

**Land:** Farmland, residential

**Comments:** Maintain size of opening when repairing.




Figure 1




Figure 2



Figure 3



Figure 4



**Figure 4:** Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04327-92