

Site ST6B: Stewiacke River (Rail crossing)

Date Assessed: 26/06/02

GPS Coordinates: N 45° 9' 24.0''
W 63° 19' 5.6''

Crossing Status: No Restriction

Road Crossing: Railway Bridge,
51.5m opening

Crossing Condition: Intact

Restriction Indicators: None

Downstream of Crossing

Creek: ~ 55m in width, smooth,
straight flow, some bank slumping

Land: Active farmland

Upstream of Crossing

Creek: ~ 55m in width, smooth,
straight flow, some bank slumping

Land: Active farmland, some marsh
vegetation

Comments: Maintain size of opening






Figure 1



Figure 2



Figure 3



Figure 4




Figure 5: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04327-94