

Site TA1B: North River

Date Assessed: 06/19/02

GPS Coordinates: N 45° 23' 14.2''
W 63° 17' 07.2''

Crossing Status: No restriction.

Road Crossing: Railbridge, steel

Crossing Condition: Structure is intact.

Restriction Indicators: None

Downstream of Crossing

Creek: Site not assessed.

Land: Farmland.

Upstream of Crossing

Creek: Site not assessed.

Land: Wooded area combined with small residential development.

Comments: Tidal influence does not seem to be an issue at this site and flow is not being restricted by this bridge.




Figure 1



Figure 2



Figure 3




Figure 4: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04312-196