

Site CCCB 21B: Sand River

Date Assessed: July 8, Aug. 27-8,
Nov. 18, 2003

GPS Coordinates: N 45° 32' 27''
W 64° 40' 38''

Crossing Status: No restriction.

Road Crossing: Steel and wood bridge with an opening of 20m.

Crossing Condition: Structure is intact.

Restriction Indicators: None

Downstream of Crossing

Creek: 25m wide creek with a turbulent flow, some bank slumping and sufficient tidal flow.

Land: No apparent land use. There is an old dyke.

Upstream of Crossing

Creek: 25m wide creek with a turbulent flow, some bank slumping and sufficient tidal flow.

Land: No apparent land use.

Comments: Maintain or enlarge opening when replacing.

No Pictures available






Figure 1: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 95005-4