

Site CCMC 26B: Advocate Harbour

Date Assessed: July 8, Aug. 27-8,
Nov. 18, 2003

GPS Coordinates: N 45° 19' 59.2''
W 64° 46' 33.3''

Crossing Status: No restriction.

Road Crossing: 40m long concrete bridge.

Crossing Condition: Structure is intact.

Restriction Indicators: None

Downstream of Crossing

Creek: Smooth flow with adequate tidal flow.

Land: There is salt marsh, wharves, beach and ocean.

Upstream of Crossing

Creek: Smooth flow with adequate tidal flow.

Land: Tidal river and salt marsh extending inland. A road has been built on one side of the marsh close to the outer edge.

Comments: No restriction, adequate flow.



Figure 1. Marsh and creek upstream of the crossing.



Figure 2. Downstream of the crossing that also shows elements of the working waterfront.




Figure 3: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04308-32