

Site CCMC 30B: Mahoney Brook

Date Assessed: July 8, Aug. 27-8,  
Nov. 18, 2003

GPS Coordinates: N 45° 22' 05.8''  
W 64° 42' 13.7''

Crossing Status: No restriction.

Road Crossing: 16m long wooden bridge.

Crossing Condition: Appears to have been Recently repaired.

Restriction Indicators: None

Downstream of Crossing

Creek: 16m wide creek with smooth flow.

Land: Salt marsh out to barrier beach.

Upstream of Crossing

Creek: 16m wide creek with smooth flow.

Land: Undeveloped river, marsh, woodland.

Comments: There is no tidal restriction of the channel.




Figure 1. The crossing as seen from the downstream beach.



Figure 2. Closer downstream view of the crossing.




Figure 3: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04311-118