

Site DC15C: Westport

Date Assessed: 26/08/04

GPS Coordinates: N 44° 15' 35.46''
W 66° 21' 6.90''

Crossing Status: Partial restriction

Road Crossing: Culvert (corrugated), 1.5m

Crossing Condition: Intact

Restriction indicators:

- Difference in water levels
- Difference in stream width
- Scour pool

Downstream of Crossing

Creek: 1m wide creek with 6m scour pool formed at mouth of crossing.

Land: Salt marsh, residential, bordered by storage facility.

Upstream of Crossing

Creek: Opens into bay.

Land: Beach and seawall.

Comments: Replace culvert with a larger opening to increase salt marsh habitat.




Figure 1. Upstream of crossing



Figure 2. Downstream view of crossing




Figure 3:
Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)