

**Site DC18B:** Long Island Wharf

**Date Assessed:** 26/08/04

**GPS Coordinates:** N 44° 23' 34.14''  
W 66° 12' 45.96''

**Crossing Status:** No restriction

**Road Crossing:** Bridge (wooden), 9.8m

**Crossing Condition:** Intact

**Restriction Indicators:** None

**Downstream of Crossing**

**Creek:** Opens into bay.


**Land:** Beach and wharf.

**Upstream of Crossing**

**Creek:** Channel narrows past wharf area where there is a rise in elevation. Creek passes through a number of driveways with culverts further upstream that do not appear to be restricting.

**Land:** Wharf and residential area.

**Comments:** Since this area is used as a harbour enlarging the opening may not be plausible. There is not a huge restriction to fish passage at this site.






**Figure 1.** Upstream view of crossing



**Figure 2.** Upstream of crossing



**Figure 3.** Downstream of crossing



**Figure 4:** Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)