

Site DC23C: Bingays Brook (Barton)

Date Assessed: 26/08/04

GPS Coordinates: N 44° 32' 33.12''
W 65° 52' 5.52''

Crossing Status: No restriction

Road Crossing: Culvert (concrete), square open bottom, 7m

Crossing Condition: Intact

Restriction Indicators: None

Downstream of Crossing

Creek: 4m wide, straight flow, some eddies and turbulent flow.

Land: Beach, bordered by residential yard and forest.

Upstream of Crossing

Creek: 4m wide rocky bottom, some turbulent flow and eddies.

Land: Wooded.

Comments: Opening size is large enough for adequate tidal flow and fish passage. There is a quick rise in elevation just after this crossing.






Figure 1. Downstream view of crossing



Figure 2. Downstream of crossing



Figure 3. Upstream of crossing




Figure 4: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)