

**Site DC25B:** Kinney Brook (Gilberts Cove)

**Date Assessed:** 26/08/04

**GPS Coordinates:** N 44° 28' 51.66''  
W 65° 57' 5.04''

**Crossing Status:** No restriction

**Road Crossing:** Bridge (wooden)

**Crossing Condition:** Intact

**Restriction Indicators:** None

**Downstream of Crossing**

**Creek:** 6m wide smooth, straight flow.


**Land:** Small salt marsh.

**Upstream of Crossing**

**Creek:** 8m wide smooth flow with small scour pool, upstream of DC24B.

**Land:** Small salt marsh.

**Comments:** Little restriction to flow or fish passage, maintain size of opening when repair is necessary.






**Figure 1.** Upstream view of crossing



**Figure 2.** Downstream of crossing



**Figure 3.** Upstream of crossing



**Figure 4:** Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)