

Site DC28B: Sissiboo River**Date Assessed:** 26/08/04**GPS Coordinates:** N 44° 24' 29.28''
W 65° 57' 24.42''**Crossing Status:** No restriction**Road Crossing:** Bridge (steel)**Crossing Condition:** Intact**Restriction Indicators:** None**Downstream of Crossing****Creek:** Smooth, straight flow.**Land:** Salt marsh bordered by forest.
Cabins on north side of river.**Upstream of Crossing****Creek:** Smooth, straight flow.**Land:** Some marsh vegetation bordered by forest.**Comments:** Maintain size of opening upon repair.



Figure 1. Upstream view of crossing



Figure 2. Downstream of crossing



Figure 3. Upstream of crossing




Figure 4: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)