

**Site DC32C:** Grosses Coques River

**Date Assessed:** 26/08/04

**GPS Coordinates:** N 44° 22' 26.7''  
W 66° 04' 27.72''

**Crossing Status:** Partial restriction

**Road Crossing:** Culvert (corrugated), 0.75m

**Crossing Condition:** Intact

**Restriction Indicators:**

- Difference in water levels
- Difference in stream width
- Scour pool

**Downstream of Crossing**

**Creek:** 5m width at opening, scour pools, slack water and angular flow.


**Land:** Salt marsh.

**Upstream of Crossing**

**Creek:** 0.5m width at opening, scour pools, slack water and angular flow.

**Land:** Salt marsh.

**Comments:** Crossing size should be enlarged to improve tidal flow and fish passage. Stream width is reduced on the upstream side of the crossing due to the small culvert opening.






**Figure 1.** Downstream view of crossing



**Figure 2.** Downstream of crossing



**Figure 3.** Upstream view of crossing



**Figure 4:** Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)