

**Site DC35B:** Duffy Brook

**Date Assessed:** 26/08/04

**GPS Coordinates:** N 44° 15' 7.23''  
W 66° 07' 50.46''

**Crossing Status:** No longer tidal

**Road Crossing:** Bridge (wooden), 2.6m

**Crossing Condition:** Intact

**Restriction Indicators:** N/A

**Downstream of Crossing**

**Creek:** Estuary


**Land:** Freshwater marsh, aboiteaux further downstream

**Upstream of Crossing**


**Creek:** Estuary

**Land:** Freshwater marsh

**Comments:** If the downstream aboiteau is ever removed reassess this crossing and any potential for restriction.



**Figure 1.** Downstream of crossing



**Figure 2: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)**