

**Site DC39B:** Metaghan River

**Date Assessed:** 26/08/04

**GPS Coordinates:** N 44° 13' 37.8''  
W 66° 07' 11.04''

**Crossing Status:** No restriction

**Road Crossing:** Bridge (steel/concrete), 26m

**Crossing Condition:** Intact

**Restriction Indicators:** None

**Downstream of Crossing**

**Creek:** 10m width, straight flow.

**Land:** Mostly wooded.

**Upstream of Crossing**

**Creek:** 10m width, straight flow.

**Land:** Wooded area, small waterfall just upstream of crossing.

**Comments:** No restriction and with rise in elevation there may be little tidal influence at this point in the system.






Figure 1. Downstream view of crossing



Figure 2. Downstream of crossing



Figure 3. Upstream of crossing showing waterfall

