

Site DC8B: Roach Brook (Smiths Cove)

Date Assessed: 26/08/04

GPS Coordinates: N 44° 36' 37.32''
W 65° 42' 53.34''

Crossing Status: No restriction

Road Crossing: Bridge (concrete), 14m

Crossing Condition: Intact

Restriction Indicators: None

Downstream of Crossing

Creek: 8m wide straight flow.

Land: Salt marsh and residential.

Upstream of Crossing

Creek: 6m wide straight flow, rise in elevation just past crossing.

Land: Wooded and residential. There are remnants of an old concrete bridge structure and a culvert just upstream possibly part of an old road. These do not appear restricting.

Comments: Maintain size of opening when repairs are made.






Figure 1. Downstream of crossing



Figure 2. Upstream of crossing



Figure 3. Upstream open bottom concrete culvert in an old road crossing which does not appear to be restricting.

