

Site DC9B: Big Joggins

Date Assessed: 26/08/04

GPS Coordinates: N 44° 36' 2.64''
W 65° 44' 39.96''

Crossing Status: No restriction

Road Crossing: Hwy Bridge (concrete) and Rail Bridge, 25m each

Crossing Condition: Intact

Restriction Indicators: None

Downstream of Crossing

Creek: 100m wide, straight flow.

Land: Beach.

Upstream of Crossing

Creek: 100m wide, straight flow.

Land: Large mudflats during low tide, some marsh vegetation along edges, bordered by forested area.

Comments: This bridge is large enough that it is not causing a restriction to tidal flow or fish passage. There is however a slight pinching of the river. Excavation of the banks around the base of the bridge could be considered.






Figure 1. Upstream view of crossing



Figure 2. Downstream rail bridge taken from site DC10C



Figure 3. Upstream of crossing




Figure 4: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)