

Site N10C: Noel Marsh

Date Assessed: 08/05/01

GPS Coordinates: N 45 17' 56.4''
W 63 43' 47.5''

Crossing Status: Partial restriction

Road Crossing: Culvert (cement), ½m

Crossing Condition: intact, debris blocking opening

Restriction Indicators:
Difference in water level
Difference in vegetation
Divergent channel
Slack water

Downstream of Crossing

Creek: 1 ½ m wide, slack water, path appears divergent from original

Land: Salt marsh

Upstream of Crossing

Creek: Straight flow

Land: Gravel fill, parking area

Comments: Culvert should be lowered and channel cleared. Debris was piled in front of opening. Fresh water drainage.






Figure 1. Upstream



Figure 2. Downstream



Figure 3. Downstream



Figure 4. Downstream




Figure 5:
 Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04321-10