

Site N17B: Bass Creek

Date Assessed: 15/05/01

GPS Coordinates: N 45 11' 55.3''
W 64 08' 00.4''

Crossing Status: No restriction

Road Crossing: Bridge (wooden)

Crossing Condition: some support failure, in need of site cleanup

Restriction Indicators: None

Downstream of Crossing

Creek: 10m wide smooth, straight flow, some bank slumping

Land: Salt marsh, rocky beach

Upstream of Crossing

Creek: 10m wide smooth, straight flow, some bank slumping

Land: Salt marsh

Comments: Bridge could use some repairs and a clean up of this site to remove debris.





Figure 1. Downstream view of crossing



Figure 2. Downstream of crossing



Figure 3. Upstream of crossing




Figure 4: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04317-154