

Site N19C: Mill Brook

Date Assessed: 15/05/01

GPS Coordinates: N 45 10' 20.6''
W 64 09' 13.4''

Crossing Status: Partial restriction

Road Crossing: Culvert (wooden box)

Crossing Condition: Intact

Restriction Indicators:

- Difference in stream width
- Difference in vegetation
- Slack water

Downstream of Crossing

Creek: 4m wide, smooth, straight flow

Land: Salt marsh, floodplain

Upstream of Crossing

Creek: 3m wide, smooth, straight flow

Land: Small marsh, mainly fresh, very little flooding of salt water

Comments: Site clean up



No Pictures Available



Figure 1: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04308-84