

Site N5B: Stirling Brook

Date Assessed: 08/05/01

GPS Coordinates: N 45 18' 39.8''
W 63 33' 37.3''

Crossing Status: No restriction

Road Crossing: Bridge (steel)

Crossing Condition: Intact

Restriction Indicators: None

Downstream of Crossing

Creek: N/A

Land: Salt marsh, partial dyking, cattle grazing

Upstream of Crossing

Creek: N/A

Land: Agricultural land

Comments: Maintain size of opening




Figure 1.



Figure 2.




Figure 3: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04320-178