

Site N7B: Mungo Brook

Date Assessed: 08/05/01

GPS Coordinates: N 45 18' 46.9''
W 63 37' 58.0''

Crossing Status: No restriction

Road Crossing: Bridge (wooden)

Crossing Condition: Intact

Restriction Indicators: None

Downstream of Crossing

Creek: 10m wide, smooth straight flow

Land: Salt marsh, some agriculture on one side, high banks on the other

Upstream of Crossing

Creek: 9m wide, smooth, straight flow.

Land: N/A

Comments: Structure does not appear restricting, maintain size of opening.




Figure 1. Downstream view of crossing



Figure 2.




Figure 3:
Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04320-173