

Site N9C: Noel Marsh

Date Assessed: 08/05/01

GPS Coordinates: N 45 17' 57.3''
W 63 43' 42.1''

Crossing Status: Complete restriction

Road Crossing: Culvert (wooden box), 2 chambers 1 ½ m each

Crossing Condition: Base tearing away slightly

Restriction Indicators:

- Difference in water level
- Bank slumping
- Difference in vegetation
- Slack water
- Scour pool

Downstream of Crossing

Creek: 3m wide, bank slumping, scour pool, slack water

Land: Salt marsh, hay straddles

Upstream of Crossing

Creek: Smooth, straight flow

Land: Freshwater creek, not in use

Comments: Base of culvert is above the high water line, culvert needs to be lowered to allow for tidal flow and fish passage.






Figure 1. Upstream



Figure 2. Downstream



Figure 3. Downstream



Figure 4. Downstream




Figure 5: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04321-10