

Site HCMB 4B: Kennetcook River (Scotch Village)

Date Assessed: 04/09/03,
05/12/03

GPS Coordinates: N 45° 03' 47.0''
W 64° 00' 17.7''

Crossing Status: No restriction.

Road Crossing: A 100m long concrete bridge.

Crossing Condition: Structure is intact.

Restriction Indicators: None

Downstream of Crossing

River: River is 70m wide with a smooth flow.

Land: Mixed marshland and agricultural land.

Upstream of Crossing

River: River is 70m wide with a smooth flow.

Land: Mixed marsh and agricultural land but with no evidence of dyking.

Comments: Maintain opening size and placement.




Figure 1: *Upstream view of the bridge.*



Figure 2: *Upstream*



Figure 3: *downstream*




Figure 4: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)



Figure 5: 2002 Aerial photograph containing tidal barrier data, (1: 10,000)