



**Site HCMB 6B:** Kennetcook River (Stanley)**Date Assessed:** 04/09/03,  
05/12/03**GPS Coordinates:** N 45° 05' 24.8''  
W 63° 56' 17.1''**Crossing Status:** No restriction.**Road Crossing:**

A 6m long wooden bridge with an opening width of 5m.

**Crossing Condition:**

Structure is old but remains intact.

**Restriction Indicators:** None**Downstream of Crossing****Creek:** 4m in width with a smooth flow.**Land:** Salt marsh is on both sides of the creek. It was or is being grazed with no protection along the banks of the creek.**Upstream of Crossing****Creek:** 4m in width with a smooth flow.**Land:** Salt marsh is on both sides of the creek.**Comments:** When repair or replacement is needed, the structure should remain a bridge with an opening width no smaller than 5m.**Figure 1:** A fence built across the creek under the bridge keeps grazing animals from going to the other side, but the banks of the creek are not protected.



**Figure 2:** Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)



**Figure 3:** 2002 Aerial photograph containing tidal barrier data, (1: 10,000)