

Site HCMB 8B: Kennetcook River (Stanley)

Date Assessed: 04/09/03,
05/12/03

GPS Coordinates: N 45° 05' 23.0''
W 63° 55' 27.2''

Crossing Status: No restriction

Road Crossing: A 22m long steel bridge with an opening width of 14m.

Crossing Condition: Structure is intact.

Restriction Indicators: None

Downstream of Crossing

Creek: 8m width with a smooth, straight flow.

Land: Marsh species present.
Agriculture use (grazing).

Upstream of Crossing

Creek: 8m width with a smooth, straight flow.

Land: Marsh species present. Evidence of old dyking and agriculture use (grazing)..

Comments: When repair or replacement is necessary, the structure should remain a bridge with an opening of at least the same dimensions there now.




Figure 1: Downstream of the bridge shows the elevation rise on one side of the river with trees and a house. The other side of the river is where the animals graze.



Figure 2: *upstream*



Figure 3: *upstream*




Figure 4: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04331-37 or 04331-36