

Site KCMB 20C: Blomidon

Date Assessed: 03/08/04

GPS Coordinates: N 45° 12' 18.3''
W 64° 22' 41.1''

Crossing Status: Partially restricted

Road Crossing: Wooden box culvert

Crossing Condition: Intact

Restriction Indicators:

- Difference in water levels
- Difference in stream width
- Scour pool
- Bank slumping

Downstream of Crossing

Creek: 2m wide opening into Pereaux Creek estuary.

Land: Salt marsh and forest.

Upstream of Crossing

Creek: Smooth straight flow, 2m width.

Land: Small wetland and forest.

Comments: Little restoration potential, small marsh upstream with little room to expand.






Figure 1. Downstream of crossing



Figure 2. Upstream of crossing




Figure 3: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)



Figure 4: 2002 Aerial photograph containing tidal barrier data, (1: 10,000)